
SAFE MONITORING OF NUT WEAR **In vertical/oblique lifting using "LVW" supports.**

Vertical / oblique movements

"**Compact Safety**" supports Group for vertical and oblique use, with insertion under the **LV support** with load bearing nut, a **loose safety LVW support** that intervenes if the threads of the load bearing nut break so as to avoid the load falling.
The system includes electric proximity signalling the at the moment needed **indicates necessity to change the load bearing nut** and verifies the integrity of the safety nut.
The system can be operated from the **QSU warning panel** or from the general machine panel fitted with test lights and effective alarms. As well as using the test button when starting the Group (from fresh) **a metal spacer half the thickness of the screw pitch should be inserted between the LV support and the proximity device to check that the warning light comes on.**

For greater simplicity and economy the same Group can be supplied without electric signalling but with **direct visual control of the supports** (see plate below).



- **ALUMINIUM PLATES to apply to the machinery for controlling wear on the nuts. The plates are supplied with the manoeuvring Groups or together with the single support referred to.**

Plate for electric control





Plate for visual control



Photos, diagrams and technical data are the exclusive property of Bimeccanica srl. All rights reserved.